

Index: G-8 Corner: CE1/16

LAND CORNER RECORD

Polk_H07

Polk-H07

State of Indiana
Hoosier National ForestTwnshp 7N Range: 1E Section: 8 2nd P.M. County

Monroe

EXISTING SURVEYS

Original Government Survey

Original Survey Evidence Found

Year Surveyed:				By:			
Original Monument:	Not Surveyed			Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded: Monroe County Surveyors Office				Year Searched: 11/26/2002 By: B. Stone			
Book: 1 Page: 314, also Date: 1856, 1872, 1898 202,552				Monument Found: 10" x 5" sediment stone standing firmly 7" above the ground			
Monument Set: 1856-stake, 1872- stone,							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
1856-W.Oak	30"	S 64 E	82 links				
1872- B. Walnut	4"	N 79 W	47 links				
1898- Ironwood	1"	S 76 E	33 links				
Limestone		N 5 W	12 links				

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The stone is located approximately 100 feet south of a hilltop on the south slope in a north-south treeline. A building on the Ransburg Boy Scout Reservation can be seen S 34 W on a ridge to the southwest. A pine stand is approximately 175 feet to the southeast. A 4" x 4" wood post with a survey monument and property boundary signs is 2 feet east.	

PERPETUATION RECORD


Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.									
Left as found									
Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.								
	Old bearing trees with tags:								
	<table> <tr> <td>Hickory</td> <td>W. Oak</td> </tr> <tr> <td>7"</td> <td>23"</td> </tr> <tr> <td>N 25 W</td> <td>N 54 E</td> </tr> <tr> <td>9.6 Ft.</td> <td>20.8 Ft.</td> </tr> </table>	Hickory	W. Oak	7"	23"	N 25 W	N 54 E	9.6 Ft.	20.8 Ft.
	Hickory	W. Oak							
	7"	23"							
	N 25 W	N 54 E							
9.6 Ft.	20.8 Ft.								
Corner Recordation:	Certificate Prepared:								
Filed and Recorded in County records:	Date:								
Book:	Page:								
Section: 8	Geodetic Coordinates: Lat./N. 39 03 19.5 Long./W 86 25 42.8								
Edited By: Robert J. Stone	Date Created: 11/26/02								

Accepted by the Monroe County Surveyor Review Board on August 6, 2019.

Index No. 68
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7 N. R. 1 E. 2nd Mer. N.F. Hoosier County Monroe State Ind
1/4 Corner common to sections 8 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>4-1980</u> By <u>Tim Cummings</u>
Where filed or recorded _____	<u>Sediment stone 8"x8"x6"</u>
Monument _____ (Original, concrete post, iron rod, etc.)	_____
_____	_____
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

☐ Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____3. Man hours spent in search 5 min

4. Do you think additional search might

(recover evidence? Yes _____ No _____)

5. Signature Tim Cummings

Relation of Evidence to Record Features Along Section Lines

Section line to sections	Object	Record distance	Measured distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Tree line N-S, E-W
app 20' S of intersection of tree lines 30'
S of ridge top. Gravel road 150' N of stone.
Stone is sediment rock 8"x6"x8" high stone
crumbles very easily by rubbing with fingers,
no markings at all.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

R. T. Cor. Tag	R. T. Cor. Tag	R. T. Cor. Tag
<u>W.D.</u>	<u>Hick.</u>	<u>Hick.</u>
<u>16"</u>	<u>6"</u>	<u>12"</u>
<u>N 51° E</u>	<u>N 24° W</u>	<u>S 14° W</u>
<u>20.56'</u>	<u>9.62'</u>	<u>30.45'</u>

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____